

FIG. 1






FIG. 2




3/24  
FIG. 3




4/24

FIG. 4




5/24  
FIG. 5




6/24

FIG. 6




7/24  
FIG. 7



8/24

FIG. 8





9/24

FIG. 9A





FIG. 9B



10/24  
FIG. 10




FIG. 11






FIG. 13





FIG. 14



15/24  
FIG. 15




FIG. 16





FIG. 17





17/24

FIG. 18




FIG. 19




FIG. 20





FIG. 21



21/24  
FIG. 22





FIG. 23



23/24

FIG. 24

61

NGOK

A

HORIZONTAL MARGIN

Mh (mm) = 0.000

VERTICAL MARGIN

Mv (mm) = Δ.ΔΔΔ

CENTER DEVIATION AMOUNT X

(mm) = □.□□□

CENTER DEVIATION AMOUNT Y

(mm) = ☆.☆☆☆

24/24

FIG. 25

